

CHEVROLET—CENTRAL OFFICE  
DIVISION OF GENERAL MOTORS CORPORATION  
DETROIT 2, MICHIGAN



**TECHNICAL SERVICE BULLETIN**  
Service and Mechanical Department



**SUBJECT:** Corvette Ventilator Window Lock - Tail  
Pipe Extension

**BULLETIN NO.:** TSB #325

**SECTION:** I

**TO:** All Chevrolet Service Personnel

November 24, 1954

SIDE DOOR VENTILATOR LOCK

A Side Door Ventilator Lock to hold the Ventilator in the closed position has been released for production and service.

PARTS DATA

Side Door Ventilator Slide Lock Unit (2 required).

PART NUMBER

3717205

INSTALLATION

Slide Clip along upper corner of ventilator window frame.

Close ventilator window and slide clip as far as possible into locked position.

With clip in locked position drill #47 (.0785) diameter hole through ventilator window frame at forward end of slot.

Carefully press pin in hole till end is flush with side of clip.

TAIL PIPE EXTENSION

A longer tail pipe extension with a baffle to deflect the exhaust gases downward to eliminate staining of the paint has been released.

PARTS DATA

Tail Pipe Extension

Entered Production 5-18-54 - Serial No. E545 002628.

PART NUMBER

3711147

POLICY

The above items may be installed to handle customer complaints.

