

NCRS 1953-1955

Chassis

Page 1 of 4

Revised 11/02

Name	Russ Uzes
VIN	1954 230/150
Model	E54S003279

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a diagonal line. If deduction is made, note reason for deduction to right of the judged item.

Score	Reason for deduction		Total
	Originality	Condition	
16. Electrical System	Originality: 36	Condition: 30	Total: 66

18 <input checked="" type="checkbox"/>	16 <input checked="" type="checkbox"/>	Generator assy, ID tag, warning label	<i>pulley broken</i>
5 <input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Generator mount & brace	
3 <input checked="" type="checkbox"/>	2 <input checked="" type="checkbox"/>	Tack drive cable @ generator or distributor	
6 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Voltage regulator & shield	
4 <input checked="" type="checkbox"/>	3 <input checked="" type="checkbox"/>	Horn relay	<i>minor rust</i>

17. Electrical Wiring Harness	Originality: 24	Condition: 19	Total: 43
--------------------------------------	-----------------	---------------	-----------

13 <input checked="" type="checkbox"/>	10 <input checked="" type="checkbox"/>	Main harness, clips; firewall to radiator support & frontal area	
3 <input checked="" type="checkbox"/>	3 <input checked="" type="checkbox"/>	Ballast resistor	
6 <input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Generator to regulator harness & clips	
2 <input checked="" type="checkbox"/>	2 <input checked="" type="checkbox"/>	Temperature sending unit/fittings & clips	

18. Battery & Cables	Originality: 40	Condition: 25	Total: 65
---------------------------------	-----------------	---------------	-----------

25 <input checked="" type="checkbox"/>	15 <input checked="" type="checkbox"/>	Delco battery	<i>cat 412 missing</i>
7 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Retainer & fasteners	
8 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Cables & felt washer	

19. Heating System	Originality: 15	Condition: 10	Total: 25
---------------------------	-----------------	---------------	-----------

10 <input checked="" type="checkbox"/>	6 <input checked="" type="checkbox"/>	Heater coolant hoses, brackets & clamps	
5 <input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Heater manual shut-off valve	

20. Wiper Motor & Washer System	Originality: 15	Condition: 15	Total: 30
--	-----------------	---------------	-----------

10 <input checked="" type="checkbox"/>	10 <input checked="" type="checkbox"/>	Wiper motor	<i>"3706280" "L" BRACKET</i>
5 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Washer system: reservoir, bracket, hoses (except foot pump)	

<i>For tabulation use only</i>			
<input type="checkbox"/> 0	+	<input type="checkbox"/> 2	= <input type="checkbox"/> 2
Deduction subtotal, page 1 of 4		Tabulator Initial	<input type="checkbox"/> ST <input type="checkbox"/> DKW

NCRS 1953-1955

Chassis

Page 2 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

21. Brake System	Originality: 20	Condition: 20	Total: 40
-------------------------	-----------------	---------------	-----------

- | | | | | |
|----|-------------------------------------|----|-------------------------------------|--|
| 10 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Master cylinder & fill cap _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Brake lines & blocks in engine compartment <i>minor rust</i> |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Park brake cable _____ |

22. Engine Compartment Blackout Paint	Originality: 20	Condition: 20	Total: 40
--	-----------------	---------------	-----------

- | | | | | |
|----|-------------------------------------|----|-------------------------------------|-----------------------------------|
| 20 | <input checked="" type="checkbox"/> | 20 | <input checked="" type="checkbox"/> | Fiberglass & blackout paint _____ |
|----|-------------------------------------|----|-------------------------------------|-----------------------------------|

23. Underside of Hood Paint & Weatherstrip	Originality: 10	Condition: 9	Total: 19
---	-----------------	--------------	-----------

- | | | | | |
|---|-------------------------------------|---|-------------------------------------|---|
| 4 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Paint color _____ |
| 3 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Paint margin _____ |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Hood weatherstrip <i>"S" LOGO MISSING</i> |

24. Hood Hardware	Originality: 20	Condition: 15	Total: 35
--------------------------	-----------------	---------------	-----------

- | | | | | |
|----|-------------------------------------|---|-------------------------------------|--|
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Forward hinges, spring assy. body hood bumpers _____ |
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Hood support _____ |
| 10 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Rear latches & hood lock assy. _____ |

25. Engine Cooling System	Originality: 15	Condition: 15	Total: 30
----------------------------------	-----------------	---------------	-----------

- | | | | | |
|---|-------------------------------------|---|-------------------------------------|--|
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Radiator fan _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Water pump pulley _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Crank balancer, pulley, timing cover & tab _____ |

26. Radiator, Supply Tank, Shroud & Hoses	Originality: 40	Condition: 35	Total: 75
--	-----------------	---------------	-----------

- | | | | | |
|----|-------------------------------------|----|-------------------------------------|--|
| 15 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Radiator, ID tag _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Radiator hoses & clamps _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Pressure cap _____ |
| 10 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Radiator support, fan shroud _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Expansion tank, fittings, hoses & clamps _____ |

For tabulation use only

+ =

Deduction subtotal, page 2 of 4

Tabulator Initial

