

NCRS 1953-1955

Chassis

Page 1 of 4

Revised 11/02

Name	Russ Uzes
VIN	1954 230/150
Model	E54S003279

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a diagonal line. If deduction is made, note reason for deduction to right of the judged item.

Score	Reason for deduction		Total
	Originality	Condition	
16. Electrical System	Originality: 36	Condition: 30	Total: 66

18 <input checked="" type="checkbox"/>	16 <input checked="" type="checkbox"/>	Generator assy, ID tag, warning label	<i>pulley broken</i>
5 <input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Generator mount & brace	
3 <input checked="" type="checkbox"/>	2 <input checked="" type="checkbox"/>	Tack drive cable @ generator or distributor	
6 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Voltage regulator & shield	
4 <input checked="" type="checkbox"/>	3 <input checked="" type="checkbox"/>	Horn relay	<i>minor rust</i>

17. Electrical Wiring Harness	Originality: 24	Condition: 19	Total: 43
--------------------------------------	-----------------	---------------	-----------

13 <input checked="" type="checkbox"/>	10 <input checked="" type="checkbox"/>	Main harness, clips; firewall to radiator support & frontal area	
3 <input checked="" type="checkbox"/>	3 <input checked="" type="checkbox"/>	Ballast resistor	
6 <input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Generator to regulator harness & clips	
2 <input checked="" type="checkbox"/>	2 <input checked="" type="checkbox"/>	Temperature sending unit/fittings & clips	

18. Battery & Cables	Originality: 40	Condition: 25	Total: 65
---------------------------------	-----------------	---------------	-----------

25 <input checked="" type="checkbox"/>	15 <input checked="" type="checkbox"/>	Delco battery	<i>cat 412 missing</i>
7 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Retainer & fasteners	
8 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Cables & felt washer	

19. Heating System	Originality: 15	Condition: 10	Total: 25
---------------------------	-----------------	---------------	-----------

10 <input checked="" type="checkbox"/>	6 <input checked="" type="checkbox"/>	Heater coolant hoses, brackets & clamps	
5 <input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Heater manual shut-off valve	

20. Wiper Motor & Washer System	Originality: 15	Condition: 15	Total: 30
--	-----------------	---------------	-----------

10 <input checked="" type="checkbox"/>	10 <input checked="" type="checkbox"/>	Wiper motor	<i>"3706280" "L" BRACKET</i>
5 <input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Washer system: reservoir, bracket, hoses (except foot pump)	

<i>For tabulation use only</i>			
<input type="checkbox"/> 0	+	<input type="checkbox"/> 2	= <input type="checkbox"/> 2
Deduction subtotal, page 1 of 4		Tabulator Initial	<input type="checkbox"/> ST <input type="checkbox"/> DKW

NCRS 1953-1955

Chassis

Page 2 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

21. Brake System	Originality: 20	Condition: 20	Total: 40
-------------------------	-----------------	---------------	-----------

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|--|------------|
| 10 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Master cylinder & fill cap | _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Brake lines & blocks in engine compartment | minor rust |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Park brake cable | _____ |

22. Engine Compartment Blackout Paint	Originality: 20	Condition: 20	Total: 40
--	-----------------	---------------	-----------

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|-----------------------------|-------|
| 20 | <input checked="" type="checkbox"/> | 20 | <input checked="" type="checkbox"/> | Fiberglass & blackout paint | _____ |
|----|-------------------------------------|----|-------------------------------------|-----------------------------|-------|

23. Underside of Hood Paint & Weatherstrip	Originality: 10	Condition: 9	Total: 19
---	-----------------	--------------	-----------

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|-------------------|--------------|
| 4 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Paint color | _____ |
| 3 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Paint margin | _____ |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Hood weatherstrip | LOGO MISSING |

24. Hood Hardware	Originality: 20	Condition: 15	Total: 35
--------------------------	-----------------	---------------	-----------

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|--|-------|
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Forward hinges, spring assy. body hood bumpers | _____ |
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Hood support | _____ |
| 10 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Rear latches & hood lock assy. | _____ |

25. Engine Cooling System	Originality: 15	Condition: 15	Total: 30
----------------------------------	-----------------	---------------	-----------

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|--|-------|
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Radiator fan | _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Water pump pulley | _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Crank balancer, pulley, timing cover & tab | _____ |

26. Radiator, Supply Tank, Shroud & Hoses	Originality: 40	Condition: 35	Total: 75
--	-----------------	---------------	-----------

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|--|-------|
| 15 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Radiator, ID tag | _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Radiator hoses & clamps | _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Pressure cap | _____ |
| 10 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Radiator support, fan shroud | _____ |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Expansion tank, fittings, hoses & clamps | _____ |

For tabulation use only

+ =

Deduction subtotal, page 2 of 4

Tabulator Initial

NCRS 1953-1955

Chassis

Page 3 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

27. Front Suspension & Steering	Originality: 25	Condition: 25	Total: 50
--	-----------------	---------------	-----------

25 1 25 Front suspension & steering & column in engine compartment _____
shock mount hardware SWB painting

28. Starter System	Originality: 25	Condition: 20	Total: 45
---------------------------	-----------------	---------------	-----------

15 12 Starter motor _____
5 4 Solenoid _____
5 4 Powerglide relay _____

29. Oil Pan & Side Cover	Originality: 15	Condition: 15	Total: 30
-------------------------------------	-----------------	---------------	-----------

10 10 Oil pan, drain plug & clutch inspection cover _____
5 5 Engine side cover (6 cyl) & attachment hardware _____

30. Transmission	Originality: 40	Condition: 21	Total: 61
-------------------------	-----------------	---------------	-----------

Judge A & C or B & C

A. Automatic Transmission

26 11 Powerglide case & bellhousing extension _____
5 4 Transmission filler tube & dipstick _____
4 3 Neutral safety switch _____

B. Manual Transmission

17 9 Manual case & tailshaft extension _____
8 4 Bellhousing _____
10 5 Clutch linkage & return spring _____

C. Cables

5 3 Speedometer cable _____

For tabulation use only

1 + 0 = 1

Deduction subtotal, page 3 of 4

Tabulator Initial ST

DPW

NCRS 1953-1955

Chassis

Page 4 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

31. Chassis & Rear Axle	Originality: 58	Condition: 57	Total: 115
------------------------------------	-----------------	---------------	------------

13	<input checked="" type="checkbox"/>	13	<input checked="" type="checkbox"/>	Frame; brake & fuel lines
3	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Frame stencil <u>missing</u>
14	<input checked="" type="checkbox"/>	14	<input checked="" type="checkbox"/>	Rear suspension, all components
8	<input checked="" type="checkbox"/>	8	<input checked="" type="checkbox"/>	Rear axle housing assy, driveshaft & rebound straps
20	<input checked="" type="checkbox"/>	20	<input checked="" type="checkbox"/>	Mufflers, tail pipes, hangers & bracket to trans (6 cyl)

32. Overall Cleanliness	Originality: None	Condition: 20	Total: 20
--------------------------------	-------------------	---------------	-----------

none 20 Cleanliness 5

Review

Judge Cal Brookbeck Judge JOHN TIDWELL
 Owner review & initial RDU Team Leader Initial KAM Judging Chairman Initial JH

For tabulation use only

3 + 2 = 5 Deduction subtotal, page 4 of 4 Tabulator Initial ST DKW

Page 1 subtotal	=	<input type="checkbox"/> 2	Tabulator initial	<input type="checkbox"/> ST	<input type="checkbox"/> DKW
Page 2 subtotal	=	<input type="checkbox"/> 2			
Page 3 subtotal	=	<input type="checkbox"/> 1			
Page 4 subtotal	=	<input type="checkbox"/> 5			
Total Deduction		<input type="checkbox"/> 10	(Subtract from 789 possible) -	<input type="checkbox"/> 10	
			Total Chassis	<input type="checkbox"/> 779	