

NCRS 1953-1955

Exterior

Page 1 of 4

Revised 11/02

Name Russ Uzes
 1954 230/150
 VIN E54S003279
 Model

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a diagonal line. If deduction is made, note reason for deduction to right of the judged item.

Score	Reason for deduction		Total
	Originality	Condition	
1. Body Color	Originality: 85	Condition: 0	Total: 85

85 None Body color (refer to Judging Reference Manual, Section 4 #12)

2. Body Paint	Originality: 45	Condition: 40	Total: 85
----------------------	-----------------	---------------	-----------

45 40 Body paint

3. Condition of Fiberglass & Component Fit	Originality: 60	Condition: 60	Total: 120
---	-----------------	---------------	------------

60 60 5 Fiberglass & body fit DASH SAG, TOP LID GAP, FRONT HOOD FIT
 CONV (DS)

4. Soft Top	Originality: 40	Condition: 40	Total: 80
--------------------	-----------------	---------------	-----------

15 15 1 Color & material
 10 10 1 Stitching & bindings WRONG STAINLESS TIPS ALL 4
 15 15 2 Window, mfg. trademark & date BUG DATE WRONG

5. Windshield Glass & Trim	Originality: 30	Condition: 30	Total: 60
---------------------------------------	-----------------	---------------	-----------

20 5 20 Windshield glass, logo & date NO LOGO/DATE
 10 10 Windshield frame, gasket & rubber end seal

6. Side Window & Ventilator Assembly	Originality: 25	Condition: 15	Total: 40
---	-----------------	---------------	-----------

10 7 Plexiglas, logo & date APR 54
 8 5 Window & ventilator frame, thumbscrew, screws & vent lock
 7 3 Rubber seals

For tabulation use only

8 + 6 = 14

Deduction subtotal, page 1 of 4

Tabulator Initial

DKW

DJ

NCRS 1953-1955

Exterior

Page 2 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

7. Cowl & Wipers	Originality: 20	Condition: 20	Total: 40
-----------------------------	-----------------	---------------	-----------

- | | | | | | | |
|---|-------------------------------------|---|---|-------------------------------------|------------------------------|---|
| 5 | <input type="checkbox"/> | 2 | 5 | <input checked="" type="checkbox"/> | Cowl vent, screen & gasket | SCREEN SHOULD BE BODY COLOR / PAINT CHIPS |
| 8 | <input checked="" type="checkbox"/> | | 8 | <input checked="" type="checkbox"/> | Wiper bezels, gaskets & arms | SCRAPE ON R/S BEZEL |
| 4 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | Wiper blades | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Washer nozzles & gaskets | |

8. Front, Rear & Side Emblems	Originality: 20	Condition: 15	Total: 35
--	-----------------	---------------	-----------

- | | | | | | | |
|----|-------------------------------------|--|---|-------------------------------------|---|--|
| 14 | <input checked="" type="checkbox"/> | | 9 | <input checked="" type="checkbox"/> | Front & rear Corvette emblems | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Script side fender nameplates | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Gold "V" on V-8 models (full credit if non-V-8) | |

9. Fuel Filler Area & Gas Cap	Originality: 10	Condition: 10	Total: 20
--	-----------------	---------------	-----------

- | | | | | | | |
|---|-------------------------------------|--|---|-------------------------------------|------------------------------|--|
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Filler area paint | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Rubber items, screws & clips | |
| 4 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | Gas cap | |

10. Grille Assembly & Radiator Frontal Area	Originality: 30	Condition: 30	Total: 60
--	-----------------	---------------	-----------

- | | | | | | | |
|----|-------------------------------------|--|----|-------------------------------------|--------------|------------------------------------|
| 7 | <input checked="" type="checkbox"/> | | 7 | <input checked="" type="checkbox"/> | Grille frame | |
| 5 | <input checked="" type="checkbox"/> | | 5 | <input checked="" type="checkbox"/> | Center bar | |
| 13 | <input checked="" type="checkbox"/> | | 13 | <input checked="" type="checkbox"/> | Teeth | |
| 2 | <input checked="" type="checkbox"/> | | 2 | <input checked="" type="checkbox"/> | Blackout | FIBERGLASS REPAIR RF RADIATOR AREA |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Horns | |

11. Front Bumpers, License Carrier & Brackets	Originality: 25	Condition: 25	Total: 50
--	-----------------	---------------	-----------

- | | | | | | | |
|----|-------------------------------------|---|----|-------------------------------------|--|--------------------|
| 11 | <input checked="" type="checkbox"/> | | 11 | <input checked="" type="checkbox"/> | Horizontal & vertical fender bumpers & bullets | |
| 9 | <input checked="" type="checkbox"/> | | 9 | <input checked="" type="checkbox"/> | Vertical bumper guards | |
| 2 | <input checked="" type="checkbox"/> | | 2 | <input checked="" type="checkbox"/> | License plate bar | WRONG BOLTS |
| 3 | <input checked="" type="checkbox"/> | 1 | 3 | <input checked="" type="checkbox"/> | Vertical bumper guard support brackets | RF BUMPERETTE BOLT |

For tabulation use only			
<input type="text" value="3"/>	+	<input type="text" value="0"/>	= <input type="text" value="3"/>
Deduction subtotal, page 2 of 4		Tabulator Initial	<input type="text" value="DKW"/> <input type="text" value="M"/>

