

NCRS 1953-1955

Exterior

Page 1 of 4

Revised 11/02

Name	Russ Uzes
	1954 230/150
VIN	E54S003279
Model	

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a diagonal line. If deduction is made, note reason for deduction to right of the judged item.

Score	Reason for deduction		Total
	Originality	Condition	
	Originality: 85	Condition: 0	Total: 85

1. Body Color

85 None Body color (refer to Judging Reference Manual, Section 4 #12)

	Originality: 45	Condition: 40	Total: 85
--	-----------------	---------------	-----------

2. Body Paint

45 40 Body paint

	Originality: 60	Condition: 60	Total: 120
--	-----------------	---------------	------------

3. Condition of Fiberglass & Component Fit

60 60 5 Fiberglass & body fit DASH SAG, ^{CONV (DS)} TOP LID GAP, FRONT HOOD FIT

	Originality: 40	Condition: 40	Total: 80
--	-----------------	---------------	-----------

4. Soft Top

15 15 1 Color & material
 10 10 1 Stitching & bindings WRONG STAINLESS TIPS ALL 4
 15 15 2 Window, mfg. trademark & date BUG DATE WRONG

	Originality: 30	Condition: 30	Total: 60
--	-----------------	---------------	-----------

5. Windshield Glass & Trim

20 5 20 Windshield glass, logo & date NO LOGO/DATE
 10 10 Windshield frame, gasket & rubber end seal

	Originality: 25	Condition: 15	Total: 40
--	-----------------	---------------	-----------

6. Side Window & Ventilator Assembly

10 7 Plexiglas, logo & date APR 54
 8 5 Window & ventilator frame, thumbscrew, screws & vent lock
 7 3 Rubber seals

For tabulation use only

8 + 6 = 14

Deduction subtotal, page 1 of 4

Tabulator Initial

DKW

DJ

NCRS 1953-1955

Exterior

Page 2 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

7. Cowl & Wipers	Originality: 20	Condition: 20	Total: 40
-----------------------------	-----------------	---------------	-----------

- | | | | | | | |
|---|-------------------------------------|---|---|-------------------------------------|------------------------------|---|
| 5 | <input type="checkbox"/> | 2 | 5 | <input checked="" type="checkbox"/> | Cowl vent, screen & gasket | SCREEN SHOULD BE BODY COLOR / PAINT CHIPS |
| 8 | <input checked="" type="checkbox"/> | | 8 | <input checked="" type="checkbox"/> | Wiper bezels, gaskets & arms | SCRAPE ON R/S BEZEL |
| 4 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | Wiper blades | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Washer nozzles & gaskets | |

8. Front, Rear & Side Emblems	Originality: 20	Condition: 15	Total: 35
--	-----------------	---------------	-----------

- | | | | | | | |
|----|-------------------------------------|--|---|-------------------------------------|---|--|
| 14 | <input checked="" type="checkbox"/> | | 9 | <input checked="" type="checkbox"/> | Front & rear Corvette emblems | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Script side fender nameplates | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Gold "V" on V-8 models (full credit if non-V-8) | |

9. Fuel Filler Area & Gas Cap	Originality: 10	Condition: 10	Total: 20
--	-----------------	---------------	-----------

- | | | | | | | |
|---|-------------------------------------|--|---|-------------------------------------|------------------------------|--|
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Filler area paint | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Rubber items, screws & clips | |
| 4 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | Gas cap | |

10. Grille Assembly & Radiator Frontal Area	Originality: 30	Condition: 30	Total: 60
--	-----------------	---------------	-----------

- | | | | | | | |
|----|-------------------------------------|--|----|-------------------------------------|--------------|------------------------------------|
| 7 | <input checked="" type="checkbox"/> | | 7 | <input checked="" type="checkbox"/> | Grille frame | |
| 5 | <input checked="" type="checkbox"/> | | 5 | <input checked="" type="checkbox"/> | Center bar | |
| 13 | <input checked="" type="checkbox"/> | | 13 | <input checked="" type="checkbox"/> | Teeth | |
| 2 | <input checked="" type="checkbox"/> | | 2 | <input checked="" type="checkbox"/> | Blackout | FIBERGLASS REPAIR RF RADIATOR AREA |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Horns | |

11. Front Bumpers, License Carrier & Brackets	Originality: 25	Condition: 25	Total: 50
--	-----------------	---------------	-----------

- | | | | | | | |
|----|-------------------------------------|---|----|-------------------------------------|--|--------------------|
| 11 | <input checked="" type="checkbox"/> | | 11 | <input checked="" type="checkbox"/> | Horizontal & vertical fender bumpers & bullets | |
| 9 | <input checked="" type="checkbox"/> | | 9 | <input checked="" type="checkbox"/> | Vertical bumper guards | |
| 2 | <input checked="" type="checkbox"/> | | 2 | <input checked="" type="checkbox"/> | License plate bar | WRONG BOLTS |
| 3 | <input checked="" type="checkbox"/> | 1 | 3 | <input checked="" type="checkbox"/> | Vertical bumper guard support brackets | RF BUMPERETTE BOLT |

For tabulation use only

+ =

Deduction subtotal, page 2 of 4

Tabulator Initial

NCRS 1953-1955

Exterior

Page 3 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

12. Headlight Assemblies	Originality: 18	Condition: 9	Total: 27
---------------------------------	-----------------	--------------	-----------

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|----------------------------------|--------------|
| 12 | <input checked="" type="checkbox"/> | 3 | <input type="checkbox"/> 2 | 6 points per bulb | DETERIORATED |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Lamp bezels | |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Headlight bucket and mesh screen | |

13. Parking Lamps	Originality: 10	Condition: 5	Total: 15
--------------------------	-----------------	--------------	-----------

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|---------------|-------------------|
| 10 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Lamp assembly | RS CRACKED GASKET |
|----|-------------------------------------|---|-------------------------------------|---------------|-------------------|

14. Body Side Trim & Moldings	Originality: 20	Condition: 20	Total: 40
--	-----------------	---------------	-----------

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|-----------------------------|----------------------------|
| 10 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Body side moldings | DRIVERS DOOR SANDING MARKS |
| 4 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Gullwing moldings | |
| 6 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Upper door garnish moldings | |

15. Rear Bumper Area	Originality: 30	Condition: 30	Total: 60
-----------------------------	-----------------	---------------	-----------

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|--|---|
| 12 | <input checked="" type="checkbox"/> | 12 | <input checked="" type="checkbox"/> | Rear fender bumpers (4 pieces each side) | |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Horizontal bumper bar | |
| 5 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Tail lamp housing assemblies | |
| 2 | <input checked="" type="checkbox"/> | 2 | <input type="checkbox"/> 1 | Trunk lock | LATCH MECH DIRTY, PLATING ON STRIKER DULL |
| 6 | <input checked="" type="checkbox"/> | 6 | <input type="checkbox"/> 1 | Exhaust extensions | CHROME PLATING WORN |

16. Rear License Plate Cove	Originality: 11	Condition: 11	Total: 22
------------------------------------	-----------------	---------------	-----------

- | | | | | | |
|---|----------------------------|---|-------------------------------------|-----------------|-------------------------|
| 3 | <input type="checkbox"/> 1 | 3 | <input type="checkbox"/> 1 | Cove paint | PAINTED OVER OLD PAINT |
| 3 | <input type="checkbox"/> 1 | 3 | <input checked="" type="checkbox"/> | Plexiglas cover | BOLTS INSTEAD OF RIVETS |
| 3 | <input type="checkbox"/> 1 | 3 | <input checked="" type="checkbox"/> | Chrome bezel | WRONG SCREWS |
| 2 | <input type="checkbox"/> 1 | 2 | <input type="checkbox"/> 1 | Water drain | GLASSED OVER |

17. Radio Antenna Ground	Originality: 5	Condition: 5	Total: 10
---------------------------------	----------------	--------------	-----------

- | | | | | | |
|---|----------------------------|---|----------------------------|----------------------------|-----------------------|
| 5 | <input type="checkbox"/> 1 | 5 | <input type="checkbox"/> 1 | Antenna cable ground strap | MISSING RUBBER SLEEVE |
|---|----------------------------|---|----------------------------|----------------------------|-----------------------|

18. Exterior Rear View Mirror	Originality: 13	Condition: 7	Total: 20
--------------------------------------	-----------------	--------------	-----------

- | | | | | | |
|----|----------------------------|---|----------------------------|-----------------|-----------------------|
| 13 | <input type="checkbox"/> 1 | 7 | <input type="checkbox"/> 1 | Exterior mirror | REPRODUCTION S/S BALL |
|----|----------------------------|---|----------------------------|-----------------|-----------------------|

For tabulation use only								
<input type="checkbox"/> 6	+	<input type="checkbox"/> 8	=	<input type="checkbox"/> 14	Deduction subtotal, page 3 of 4	Tabulator Initial	<input type="checkbox"/> DKW	<input type="checkbox"/> [Signature]

NCRS 1953-1955

Exterior

Page 4 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____

19. Wheels (including spare) Originality: 25 Condition: 20 Total: 45

25 4 20 Wheels, weights, valve stems & caps *SHOULD BE METAL WRONG CAPS/WEIGHTS*

20. Wheel Covers Originality: 24 Condition: 21 Total: 45

16 16 Wheel covers *LR DING/RF REPAIR*
 8 4 5 2 Ornaments & positioning *REPRODUCTION SPINNERS NO CHROME*

21. Tires Originality: 30 Condition: 30 Total: 60

30 3 30 Tires *DOT*

22. Underbody & Wheelhouses Originality: 20 Condition: 15 Total: 35

6 5 Underbody *BOLT PULLED THRU*
 8 6 Wheelhouses, blackout & undercoating
 6 4 Splash pan assembly & seal

23. Overall Cleanliness Originality: None Condition: 20 Total: 20

none 20 Overall cleanliness

Review

Judge *Soe Calcano* Judge *Don Mullenhoff* *Rick Gowen*
Don Mullenhoff *Rick Gowen*

Owner review & initial *RDH* Team Leader Initial *KAM* Judging Chairman Initial *JH*

For tabulation use only

11 + 2 = 13 Deduction subtotal, page 4 of 4 Tabulator Initial *DKW* *JH*

Page 1 subtotal	=	<input type="checkbox"/> 14	Tabulator initial	<input type="checkbox"/> <i>DKW</i>	<input type="checkbox"/> <i>JH</i>
Page 2 subtotal	=	<input type="checkbox"/> 3			
Page 3 subtotal	=	<input type="checkbox"/> 14			
Page 4 subtotal	=	<input type="checkbox"/> 13	(Subtract from 1074 possible) -	<input type="checkbox"/> 44	
Total Deduction		<input type="checkbox"/> 44	Total Exterior	<input type="checkbox"/> 1030	