

NCRS 1953-1955

Interior

Page 1 of 4

Revised 11/02

Name	Russ Uzes
VIN	1954 230/150
Model	E54S003279

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a diagonal line. If deduction is made, note reason for deduction to right of the judged item.

Score		Reason for deduction	Originality	Condition	Total
Originality	Condition				
1. Seats			Originality: 45	Condition: 41	Total: 86

40	<input checked="" type="checkbox"/>	38	<input checked="" type="checkbox"/>	Seats (10 per cushion)	<i>No burlap liners ^{left} on seat bottoms, (minor flap DK)</i>
5	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Drivers seat adjustment lever	

2. Carpeting			Originality: 35	Condition: 30	Total: 65
---------------------	--	--	-----------------	---------------	-----------

10	<input checked="" type="checkbox"/>	10	<input checked="" type="checkbox"/>	Color	
15	<input checked="" type="checkbox"/>	10	<input checked="" type="checkbox"/>	Carpet weave	
5	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Seams, bindings, & fit	
5	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Dimmer bezel, heel pad & carpet retaining screws	<i>Dimmer bezel should be rubber,</i>

3. Transmission & Console Area			Originality: 17	Condition: 8	Total: 25
---	--	--	-----------------	--------------	-----------

10	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Shifter, knob and housing	<i>Knob dinged, should have worn out on boot housing</i>
7	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Boot & bezel	

4. Instrument Panel Crown Pad			Originality: 10	Condition: 10	Total: 20
--------------------------------------	--	--	-----------------	---------------	-----------

7	<input checked="" type="checkbox"/>	7	<input checked="" type="checkbox"/>	Color & material	<i>(u)</i>
3	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Sewing & fit	

5. Int. Mirror & Defroster Outlets			Originality: 15	Condition: 10	Total: 25
---	--	--	-----------------	---------------	-----------

10	<input checked="" type="checkbox"/>	7	<input checked="" type="checkbox"/>	Interior Mirror	
5	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Defroster Outlets	

6. Upper & Lower Instrument Panel Paint			Originality: 20	Condition: 10	Total: 30
--	--	--	-----------------	---------------	-----------

10	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Upper panel color & gloss	<i>minor crack in paint (R)</i>
10	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Lower panel color	<i>Paint chips around courtesy (L), original chips painted over</i>

For tabulation use only					
<input type="text" value="2"/>	+	<input type="text" value="5"/>	=	<input type="text" value="7"/>	Deduction subtotal, page 1 of 4
			Tabulator Initial	<input type="text" value="DKW"/>	<input type="text" value="ST"/>

NCRS 1953-1955

Interior

Page 2 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

7. Steering Wheel, Turn Signal & Mast Originality: 18 Condition: 14 Total: 32

- discoloration on back of wheel,*
- | | | | | |
|----|-------------------------------------|---|-------------------------------------|---|
| 12 | <input checked="" type="checkbox"/> | 8 | <input checked="" type="checkbox"/> | Steering wheel, horn ring & emblem <i>Crazing on emblem, chrome missing on ring</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Turn signal housing & lever <i>No lock washer, (paint missing on hub screw)</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Steering column mast <i>white overspray</i> |

8. Instruments & Controls Originality: 33 Condition: 33 Total: 66

- | | | | | |
|----|-------------------------------------|----|-------------------------------------|---|
| 21 | <input checked="" type="checkbox"/> | 21 | <input checked="" type="checkbox"/> | Tach, speedometer, clock & 4 gauges <i>beautiful original, minor aging on white plastic</i> |
| 4 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Ignition switch & lighter |
| 8 | <input checked="" type="checkbox"/> | 8 | <input checked="" type="checkbox"/> | Light, wiper, choke & heater controls |

9. Radio Originality: 21 Condition: 13 Total: 34

- | | | | | |
|----|-------------------------------------|---|-------------------------------------|--|
| 10 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Radio receiver & knobs |
| 6 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Speaker / power supply unit |
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Speaker grille <i>(paint wear on emblem)</i> |

10. Pedals & Area Under Dash Originality: 17 Condition: 16 Total: 33

- | | | | | |
|---|-------------------------------------|---|-------------------------------------|---|
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Heater; defroster hoses & ducts <i>Heater housing should be black, plain is incorrect</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Cowl vent mechanism & hood release <i>vent knob should white plastic, hood release bracket ^{is} pitted</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Insulation |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Wiring |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Pedals & pads incl ww foot pump assembly |

11. Park Brake, Courtesy Lamp, & Door Switch Originality: 10 Condition: 6 Total: 16

- | | | | | |
|---|-------------------------------------|---|-------------------------------------|--|
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Park brake, handle & alarm <i>incorrect fastener on handle, and it's rusty</i> |
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Courtesy lamp & door switches |

For tabulation use only

<input type="text" value="6"/>	+	<input type="text" value="4"/>	=	<input type="text" value="10"/>	Deduction subtotal, page 2 of 4	Tabulator Initial <input type="text" value="DKW"/>	<input type="text" value="57"/>
--------------------------------	---	--------------------------------	---	---------------------------------	---------------------------------	--	---------------------------------

