

NCRS 1953-1955

Interior

Page 1 of 4

Revised 11/02

Name	Russ Uzes
VIN	1954 230/150
Model	E54S003279

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a diagonal line. If deduction is made, note reason for deduction to right of the judged item.

Score		Reason for deduction	Originality	Condition	Total
Originality	Condition				
1. Seats			Originality: 45	Condition: 41	Total: 86

40	<input checked="" type="checkbox"/>	38	<input checked="" type="checkbox"/>	Seats (10 per cushion)	<i>No burlap liners ^{left} on seat bottoms, (minor flap DK)</i>
5	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Drivers seat adjustment lever	

2. Carpeting			Originality: 35	Condition: 30	Total: 65
---------------------	--	--	-----------------	---------------	-----------

10	<input checked="" type="checkbox"/>	10	<input checked="" type="checkbox"/>	Color	
15	<input checked="" type="checkbox"/>	10	<input checked="" type="checkbox"/>	Carpet weave	
5	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Seams, bindings, & fit	
5	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Dimmer bezel, heel pad & carpet retaining screws	<i>Dimmer bezel should be rubber,</i>

3. Transmission & Console Area			Originality: 17	Condition: 8	Total: 25
---	--	--	-----------------	--------------	-----------

10	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Shifter, knob and housing	<i>Knob dinged, should have worn out on boot housing</i>
7	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Boot & bezel	

4. Instrument Panel Crown Pad			Originality: 10	Condition: 10	Total: 20
--------------------------------------	--	--	-----------------	---------------	-----------

7	<input checked="" type="checkbox"/>	7	<input checked="" type="checkbox"/>	Color & material	<i>(u)</i>
3	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Sewing & fit	

5. Int. Mirror & Defroster Outlets			Originality: 15	Condition: 10	Total: 25
---	--	--	-----------------	---------------	-----------

10	<input checked="" type="checkbox"/>	7	<input checked="" type="checkbox"/>	Interior Mirror	
5	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Defroster Outlets	

6. Upper & Lower Instrument Panel Paint			Originality: 20	Condition: 10	Total: 30
--	--	--	-----------------	---------------	-----------

10	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Upper panel color & gloss	<i>minor crack in paint (R)</i>
10	<input checked="" type="checkbox"/>	5	<input checked="" type="checkbox"/>	Lower panel color	<i>Paint chips around courtesy (L), original chips painted over</i>

For tabulation use only					
<input type="text" value="2"/>	+	<input type="text" value="5"/>	=	<input type="text" value="7"/>	Deduction subtotal, page 1 of 4
			Tabulator Initial	<input type="text" value="DKW"/>	<input type="text" value="ST"/>

NCRS 1953-1955

Interior

Page 2 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

7. Steering Wheel, Turn Signal & Mast Originality: 18 Condition: 14 Total: 32

- discoloration on back of wheel,*
- | | | | | |
|----|-------------------------------------|---|-------------------------------------|---|
| 12 | <input checked="" type="checkbox"/> | 8 | <input checked="" type="checkbox"/> | Steering wheel, horn ring & emblem <i>Crazing on emblem, chrome missing on ring</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Turn signal housing & lever <i>No lock washer, (paint missing on hub screw)</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Steering column mast <i>white overspray</i> |

8. Instruments & Controls Originality: 33 Condition: 33 Total: 66

- | | | | | |
|----|-------------------------------------|----|-------------------------------------|---|
| 21 | <input checked="" type="checkbox"/> | 21 | <input checked="" type="checkbox"/> | Tach, speedometer, clock & 4 gauges <i>beautiful original, minor aging on white plastic</i> |
| 4 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Ignition switch & lighter |
| 8 | <input checked="" type="checkbox"/> | 8 | <input checked="" type="checkbox"/> | Light, wiper, choke & heater controls |

9. Radio Originality: 21 Condition: 13 Total: 34

- | | | | | |
|----|-------------------------------------|---|-------------------------------------|--|
| 10 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Radio receiver & knobs |
| 6 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Speaker / power supply unit |
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Speaker grille <i>(paint wear on emblem)</i> |

10. Pedals & Area Under Dash Originality: 17 Condition: 16 Total: 33

- | | | | | |
|---|-------------------------------------|---|-------------------------------------|---|
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Heater; defroster hoses & ducts <i>Heater housing should be black, plain is incorrect</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Cowl vent mechanism & hood release <i>vent knob should white plastic, hood release bracket ^{is} pitted</i> |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Insulation |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Wiring |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Pedals & pads incl ww foot pump assembly |

11. Park Brake, Courtesy Lamp, & Door Switch Originality: 10 Condition: 6 Total: 16

- | | | | | |
|---|-------------------------------------|---|-------------------------------------|--|
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Park brake, handle & alarm <i>incorrect fastener on handle, and it's rusty</i> |
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Courtesy lamp & door switches |

For tabulation use only

<input type="text" value="6"/>	+	<input type="text" value="4"/>	=	<input type="text" value="10"/>	Deduction subtotal, page 2 of 4	Tabulator Initial <input type="text" value="DKW"/>	<input type="text" value="57"/>
--------------------------------	---	--------------------------------	---	---------------------------------	---------------------------------	--	---------------------------------

NCRS 1953-1955

Interior

Page 3 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

12. Door opening, Weatherstripping	Originality: 21	Condition: 21	Total: 42
---	-----------------	---------------	-----------

- | | | | | | | | |
|---|-------------------------------------|---|---|-------------------------------------|------------------------------------|---|---|
| 4 | <input checked="" type="checkbox"/> | 2 | 4 | <input checked="" type="checkbox"/> | Door jambs, hinges, lock pillars | <i>Paint excessive and too glossy</i> | |
| 4 | <input checked="" type="checkbox"/> | 1 | 4 | <input checked="" type="checkbox"/> | Door latches & strikers | <i>Screws should be painted</i> | |
| 4 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | 2 | Sill plates | <i>Scratched & worn Original!!!</i> |
| 6 | <input checked="" type="checkbox"/> | | 6 | <input checked="" type="checkbox"/> | Weatherstrip (doors & cowl gutter) | <i>No yellow glue, black mastic evident</i> | |
| 3 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Upholstered lock pillar panels | <i>(minor scuff each)</i> | |

13. Door Panels & Kick Panels	Originality: 35	Condition: 30	Total: 65
--	-----------------	---------------	-----------

- | | | | | | | | |
|----|-------------------------------------|---|---|-------------------------------------|-------------------------------------|---|---|
| 10 | <input checked="" type="checkbox"/> | | 9 | <input checked="" type="checkbox"/> | Door panel vinyl & attaching screws | | |
| 4 | <input checked="" type="checkbox"/> | | 3 | <input checked="" type="checkbox"/> | Hinged package compartment | | |
| 6 | <input checked="" type="checkbox"/> | 1 | 5 | <input checked="" type="checkbox"/> | Cowl side kick panels & windlace | <i>forward edge stitching should echo curve</i> | |
| 5 | <input checked="" type="checkbox"/> | | 5 | <input checked="" type="checkbox"/> | 1 | Painted upper door trim & inner door pulls | <i>Paint mottled</i> |
| 10 | <input checked="" type="checkbox"/> | 1 | 8 | <input checked="" type="checkbox"/> | 2 | Ashtray & escutcheons; door & side curtain releases | <i>releases scratch, aged, wonderful orig. fit escutcheon @ door pull</i> |

14. Top Cover Trim, Separator & Compartment	Originality: 15	Condition: 15	Total: 30
--	-----------------	---------------	-----------

- | | | | | | | |
|---|-------------------------------------|--|---|-------------------------------------|-------------------------------------|--|
| 4 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | End straps | |
| 6 | <input checked="" type="checkbox"/> | | 6 | <input checked="" type="checkbox"/> | Top cover & seat separator moldings | |
| 5 | <input checked="" type="checkbox"/> | | 5 | <input checked="" type="checkbox"/> | Seat separator | |

15. Soft Top	Originality: 45	Condition: 30	Total: 75
---------------------	-----------------	---------------	-----------

- | | | | | | | | |
|------|-------------------------------------|---|---|-------------------------------------|-----------------------|---------------|--|
| 9 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | Front latches | | |
| 10 | <input checked="" type="checkbox"/> | | 5 | <input checked="" type="checkbox"/> | Rear latches | | |
| 11 | <input checked="" type="checkbox"/> | 2 | 6 | <input checked="" type="checkbox"/> | 1 | Bows | <i>Paint chipped and should be tan</i> |
| 5 | <input checked="" type="checkbox"/> | | 5 | <input checked="" type="checkbox"/> | Spring loaded flipper | | |
| 5 | <input checked="" type="checkbox"/> | | 5 | <input checked="" type="checkbox"/> | Front header seal | | |
| KH 5 | <input checked="" type="checkbox"/> | 5 | 5 | <input checked="" type="checkbox"/> | 5 | Rear bow seal | <i>Bow seal missing</i> |

16. Trunk Section	Originality: 24	Condition: 20	Total: 44
--------------------------	-----------------	---------------	-----------

- | | | | | | | | |
|----|-------------------------------------|---|----|-------------------------------------|---|-------------------|--|
| 15 | <input checked="" type="checkbox"/> | 1 | 12 | <input checked="" type="checkbox"/> | Fiberglass, trunk color & paint application | <i>Too smooth</i> | |
| 4 | <input checked="" type="checkbox"/> | | 4 | <input checked="" type="checkbox"/> | Weatherstrip | | |
| 5 | <input checked="" type="checkbox"/> | 2 | 4 | <input checked="" type="checkbox"/> | 1 | Wiring & antenna | <i>Rubber sleeve missing, coating deteriorated, solder excessive</i> |

John Kennedy

For tabulation use only							
<input type="text" value="15"/>	+	<input type="text" value="12"/>	=	<input type="text" value="27"/>	Deduction subtotal, page 3 of 4	Tabulator Initial <input type="text" value="DKW"/>	<input type="text" value="57"/>

NCRS 1953-1955

Interior

Page 4 of 4

Revised 11/02

Name	_____
VIN	_____
Model	_____ Year _____

17. Hinges, Latches, Division Panel Originality: 27 Condition: 25 Total: 52

10	<input checked="" type="checkbox"/>	10	<input checked="" type="checkbox"/>	Hinges & latching hardware	<i>Corrosion on hardware</i>
8	<input checked="" type="checkbox"/>	7	<input checked="" type="checkbox"/>	Division panel & paint	<i>Phillips missing @ base</i>
3	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Screws & clips	
6	<input checked="" type="checkbox"/>	6	<input checked="" type="checkbox"/>	Desiccant box & side window storage bag	<i>longer with selvedge edge bag center flap needs to be</i>

18. Trunk Mat, Spare Cover & Bolt Originality: 30 Condition: 25 Total: 55

15	<input checked="" type="checkbox"/>	15	<input checked="" type="checkbox"/>	Trunk mat	<i>No holdown or julien code</i>
10	<input checked="" type="checkbox"/>	6	<input checked="" type="checkbox"/>	Cover	<i>pods worn</i>
5	<input checked="" type="checkbox"/>	4	<input checked="" type="checkbox"/>	Bolt & label	

19. Jack, Handle & Lug Wrench Originality: 32 Condition: 25 Total: 57

15	<input checked="" type="checkbox"/>	10	<input checked="" type="checkbox"/>	Jack	<i>Star rivets need mashing</i>
12	<input checked="" type="checkbox"/>	12	<input checked="" type="checkbox"/>	Jack handle & lug wrench	
5	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Hold down clips	

20. Overall Cleanliness Originality: none Condition: 20 Total: 20

none 20 Overall cleanliness

Review

Judge Judge
 Owner review & initial Team Leader Initial Judging Chairman Initial

For tabulation use only

+ = Deduction subtotal, page 4 of 4 Tabulator Initial

Page 1 subtotal	=	<input type="text" value="7"/>	Tabulator initial	<input type="text" value="DKW"/>	<input type="text" value="ST"/>
Page 2 subtotal	=	<input type="text" value="10"/>			
Page 3 subtotal	=	<input type="text" value="27"/>			
Page 4 subtotal	=	<input type="text" value="6"/>			
Total Deduction		<input type="text" value="50"/>	(Subtract from 872 possible) -	<input type="text" value="50"/>	
			Total Interior	<input type="text" value="822"/>	